



Haas Factory Outlet

A DIVISION OF SIRCO MACHINERY CO. LTD.

40 Jutland Road Toronto, Ontario M8Z 2G9 Phone: 416-255-3503 Fax: 416-255-9502 Email: service@sircomachinery.com

Company: B.C. Instruments Inc.

Address: 41 Proctor Road

City: Schomberg

Region: Ontario **Postal:** L0G 1T0

Contact: Paul Mikucki

Phone: 905-939-7323

Cust Ref: CBCIN00

Engineer: Rumen Anev

Job Status: Completed

Email: paulm@bc-instruments.com

| <u>Builder</u> | <u>Model</u> | <u>Serial</u> | <u>Installed</u> | <u>Warranty Date</u> |
|----------------|-------------------|---------------|------------------|----------------------|
| Haas | UMC-750SS 1152535 | 1152535 | Aug 07 2018 | Aug 07 2019 |

SR #: S-236383

Billing: Paid Service

Service Type: Machine Repair

PO:

| <u>Date</u> | <u>Arrived</u> | <u>Finished</u> | <u>Onsite</u> | <u>Non Bill</u> | <u>Travel</u> | <u>See SR</u> |
|-------------|----------------|-----------------|---------------|-----------------|---------------|---------------|
| May 27 2024 | 9:30 AM | 2:15 PM | 4.75 | | 1.50 | |

Reported Issue: Machine Inspection (requested by Joe Tahan at CNC Used Machines)

Observations

Alarm Codes:

Status: Machine Running

Machine's inspection was done, according to requirements of "Service Inspection Report" of CNC Used Machine Inc. The results are available in attached files.

Problem Determined: mentioned in the inspection report

Tests Performed: inspection

Corrective Action: corrections

| <u>Qty</u> | <u>Part Number</u> | <u>Part Description</u> | <u>Returned</u> | <u>Inv Loc</u> |
|------------|--------------------|-------------------------|-----------------|----------------|
|------------|--------------------|-------------------------|-----------------|----------------|

Printed Name: Paul Mikucki

Signature:

Title: NO LONGER WITH COMPANY